

EMERGENCY RESPONSE

- Lighting strikes Bank Branch
- HCI Secured Site
- HCI Rebuilds – Saving Time & Money
- Branch Re-Opened within two weeks

Union Federal Bank
Plainfield, IN

Opportunity/Challenge

On June 8, 2002, lightning struck the north end of the Union Federal Bank Branch causing fire in the attic space. The resulting damage required replacement of the roof, the exterior walls, all new finishes, new drive-thru tubes, and clean-up of damaged furnishings.

Solution

Hokanson Companies, Inc. (HCI) personnel were at the site within 30 minutes. Once firefighters declared the site safe, we called in appropriate contractors, relocated personnel and equipment to a trailer, and set up the trailer so that the bank could reopen in two days. We began reconstruction on the building, coordinated insurance claims, and worked with bank personnel on repairs to equipment, fixtures, and repair/replacement of furnishings.

Approximately 75% of the trusses were replaced in the building. All finishes of the occupied space and many interiors walls were replaced as well, in the best way possible to match what was existing.

Results

Hokanson Companies, Inc. had a newly remodeled branch open within two weeks, with very little disruption of service during those weeks. HCI's quick response time and thorough renovation process provided a quick solution for the branch.

